BLOCK 03



#HeatTreatment TECNOLOGY AND FRIENDS. WITHOUT WHOM IT DOESN'T MAKE SENS

09.00 - 09.05 a.m. | 03.00 - 03.05 p.m. | 07.00 - 07.05 p.m. **OPENING OF THE EVENT**

09.05 - 09.25 a.m. | 03.05 - 03.25 p.m. | 07.05 - 07.25 p.m.

High Temperature Solution Nitriding of Stainless Steel and Titanium

09.25 - 09.35 a.m. | 03:25 - 03.35 p.m. | 07:25 - 07.35 p.m.

Technology Transfer From Atmosphere to Vacuum, Quality Improvement

09.35 - 09.45 a.m. | 03.35 - 03.45 p.m. | 07.35 - 07.45 p.m.

BREAK

09.45 - 10.10 a.m. | 03.45 - 04.10 p.m. | 07:45 - 08.10 p.m.

HeatTreatment of Fasteners. How is it done?

10.10 - 10.20 a.m. | 04.10 - 04.20 p.m. | 08:10 - 08.20 p.m.

Practice Makes Perfect Brazing

10:20 - 10:30 a.m. | 04:20 - 04:30 p.m. | 08:20 - 08:30 p.m.

BREAK

10.30 - 11.10 a.m. | 04.30 - 05.10 p.m. | 08.30 - 09.10 p.m.

Hot Work Tools #HeatTreatment